



Core System



Marshy System



Transmission Pipeline/
Horizontal Wells



700' 1400'

Figure 1

GELMAN SCIENCES, INC.

Selected Features

Site of Environmental Contamination
Scio Township, Washtenaw County
Prepared by Michigan Department of
Environmental Quality, Remediation
And Redevelopment Division, Sept. 2003

